

INSTRUMENTUnit - IBasics of MeasurementsMeasurement

It is an act of comparison of unknown quantity with a known predefined accurate standard quantity.

Application of Measurements

- 1) For recording or observing the output of a process.
- 2) To control a process / operation
- 3) For analysing Purpose.


Methods of Measurements

It can be broadly classified into two categories

i) Direct Measurement
It includes comparison with standard quantities finding the unknown magnitude.
E.g.: Simple weigh balance.
Potentiometer

iii) Indirect Measurement
It includes instruments for measuring unknown magnitude.
E.g.: Voltmeter,
Ammeter.

Types of Instruments



The ammeter, Voltmeter, wattmeter are the examples electrical Instrument. The electronic instrument has quick response time. The instrument provides the quick responses as compared to the electrical and mechanical instrument.

The ammeter, Voltmeter, ammeter measures the current voltmeter measures the voltage.

Specifications Of Instruments:-

Accuracy

- a) Accuracy as Percentage of full scale reading. In case of instrument having scale the accuracy can be expressed as percentage of full scale reading.
- b) Accuracy of Percentage of true value of quantity being measured

$$\frac{\text{Measured Value} \times 100}{\text{True Value}}$$

Point Accuracy

Such accuracy is specified at only one particular point of scale. It does not give any information about accuracy at any other point of scale.

Precision

It is the measure of consistency or Repeatability of measurements. It denotes the closeness with which individual measurements are departed or distributed about the average of no. of measured values.

Sensitivity

It is the ratio of the change in the input of an instrument to a change in the value of the quantity to be measured.

$$\text{Sensitivity} = \frac{\Delta y_o}{\Delta x_i}$$

Resolution

It is the smallest measurable input change. The resolution of an instrument is also referred as discrimination of the instrument.

Range

The minimum and maximum values of a quantity for which an instrument is designed to measure is called its range.

Error in Measurements

1) Systematic Error

These types of systematic errors are generally categorised into three types.

- Observational Error
- Environmental Error
- Instrumental Error

• Observational Error

The observation error may occur due to the fault study of the instrument reading.

• Environmental Error

It is happen due to the outside situation of the measuring instrument.

Instrumental Error

It is happen due to ~~some~~ inherent limitation of Devices, abuse of apparatus, Effect of loading.

2) Gross Errors

It can be defined as physical errors in analysis apparatus or calculating and recording measurement outcomes.

3) Random Errors

This type of error is constantly there in a measurement which is occurred by essentially random oscillations in the apparatus measurement analysis.

$$\text{Absolute Error} = |V_A - V_E|$$

$$\text{Percentage Error} = \left(\frac{|V_A - V_E|}{V_E} \right) \times 100$$

$$\text{Relative Error} = \frac{\text{Absolute Error}}{\text{Actual Value}}$$

Sources of Errors

- 1) Poor design
- 2) Poor Maintenance
- 3) Certain design limitations
- 4) Change in process parameters, irregularities, upsets etc.
- 5) Error caused by person operating the instrument


Limiting Errors

The limited deviation of the measured value from the true value is known as the limiting error. Such type of error is fixed on the instrument. The value could be atleast but never zero.

Loading Effect

Loading Effect is the degree to which a measurement impacts electrical properties of a circuit. It is an ideal measuring system

"किसी मापन प्रणाली की Input signal की ठीक प्रकार रिकॉर्ड अथवा Control ना करने की क्षमता को Loading Effect कहते हैं"



$$\text{Loading Effect} = \text{True Voltage} - \text{Apparent Voltage}$$

Importance And Application of Standards and Calibration

Whenever a new piece of measurement equipment is manufactured it must first be calibrated to the required standard before it is used.

There is a vast array of measurement equipment. Some devices may be small, simple. Each measurement device will have its standards and tolerances. The frequency of the re-calibration will vary from

device to device.

The piece of measurement equipment will be checked and realigned to the original measurement standard.

Servicing and calibration are vital to the main accuracy of the readings measurements.

Measurement Standard

A material measure measuring instrument reference material or measuring system intended to define. Definition of the standard to be fixed and correct.

Calibration

The goal of calibration is to minimise any measurement uncertainty by ensuring the accuracy of test equipment. Calibration quantifies and controls errors or uncertainties measurement processes to an acceptable level.


Unit-IIVoltage, Current and Resistance Measurement


Principles of Operation and Construction of Permanent Magnet Moving coil Galvanometer (PMMC) Instrument.

Principle of Working.

When a current carrying conductor is placed in a magnetic field, it experiences a force and tends to move in the direction. It is also called (d'Arsonval).

इस प्रकार के मापक यंत्रों में एक स्थायी चुम्बकीय क्षेत्र में एक Pivot रहती है यह Aluminium की Bobbin पर लिपटी होती है, मापी जाने वाली धारा अथवा Voltage इस कुण्डली को प्रवाहित की जाती है स्थायी चुम्बक Alcomax अथवा Alnico के बनाये जाते हैं,

Construction



Moving coil Galvanometer

A coil of thin wire is mounted on an Al. frame positioned between the poles of U shaped permanent magnet which is made up of alloys. The coil is pivoted on the jewelled bearing and thus the coil is free to rotate. The current is fed to the coil through spiral springs which are two in number. The coil which carries a current which is to be measured moves in a strong magnetic field produced by a permanent magnet and a pointer is attached to the spindle which shows the measured value.

Advantages :

- The PMMC has a high torque to weight ratio.
- It produces no losses due to hysteresis.

Disadvantages

- It is very delicate and sometimes uses AC circuit with a rectifier.
- It may show an error due to loss of magnetism of permanent magnet.

Moving Iron Type Instruments

सामान्य रूप से प्रयोगशाला में AC/DC पर प्रयुक्त कि जाने वाले Ammeter And Voltmeter Moving Iron Type होते हैं।

- Moving Iron Instruments are of two types
- Attraction type moving iron instruments.
 - Repulsion type moving iron instruments

Attraction Type Moving Iron Instruments

When a soft iron piece (vane) is placed in the M.F. of a current carrying coil then the piece is attracted towards the center of the coil.

Repulsion Type Moving Iron Instruments

The basic principle of a repulsion type moving iron instruments is that the repulsive forces will act when two similarly magnetized iron pieces are placed near each other.

Measurement of d.c voltage and current.

एक Basic PMMC (d'Arsonval) Type यंत्र के श्रेणी में प्रतिरोध connect करने पर यह Voltmeter में परिवर्तित हो जाता है। मल्टीप्लायर के अनुसार किसी यंत्र के श्रेणी में प्रयुक्त

जिसे जानने वाला प्रतिरोध है जो यंत्र की Voltage मापन की Range बढ़ाता है। मीटर R_m का श्रेणी संयोजन उस परिपथ में संयोजित किया जाता है।



I_m = मीटर के Full Scale deflection हेतु धारा

R_m = मीटर का आंतरिक प्रतिरोध

R_s = मल्टीप्लायर का प्रतिरोध

V = मापी जाने वाली Voltage

Mili-Volt Measurement

We can measure millivolt with some voltmeter and multimeter.

Step-1

Plug red probe to +v hole.

Step-2

Plug black to -v hole.

Step-3

Turn the dial to mili volt. The setting should be close but not over the maximum voltage.

Step-4

Turn your meter ON.


Step-5

Hold the insulated handles of your probes. Touch red to +ve side of DC circuit or AC circuit and black probe to -ve.

Step-6

Read the measurement.

Measurement of DC Current



- The idea is to insert an accurately known resistance R in series with a circuit to create a voltage proportional to the current flow.
- 1) A resistance big enough to get a decent size voltage level.
 - 2) A resistance small enough to avoid significantly affecting the circuit operation.

For the $200\mu A$ range only R_1 is closed.
The current flows through all resistors R_1, R_2, R_3, R_4 for

$$R_s = 900 + 90 + 9 + 1$$

$$= 1K$$

The measured voltage V_{61}
 $R_s \cdot I_m$

$$1K \cdot 200 \mu A \\ = 200mV$$


$$R_S = 10hm$$

The measured voltage at V_{C4}

$$V_m = R_S \cdot I_m$$

$$1 \cdot 200mA \\ = 200mV$$

Measure DC Volts.



The resistance value look intuitively

$$R_A = 900K + 90K + 9K + 1M$$

$$R_B = 9M$$

A simple divider

$$V_o = R_B / (R_A + R_B) = 1M / (1M + 9M) = 1/10$$

Resistors down

$$R_A = 90K + 9K + 1K = 0.1M$$

$$R_B = 9M + 900K = 9.9M$$

Multimeter


It is an electronic measuring instrument that combines several measurement functions in one unit.

Types of Multimeter

- 1) Analog Multimeter
- 2) Digital Multimeter.

1) Analog Multimeter


Analog Multimeter use a microammeter with a moving pointer to display reading.



Analog Multimeter

2) Digital Multimeter

It has numeric display and may also show a graphical bar representing the measured value.




Digital Multimeter

Measurement of Voltage Using Multimeter


- 1) Power off the circuit.
- 2) Plug the black Prob to -ve com
- 3) Plug red Prob to +ve hole.
- 4) Select AC or DC volt and pick range to required accuracy.
- 5) A multimeter must be connected in parallel in order to measure voltage. The two test probe connect in parallel.
- 6) Touch the black probe against the first point.

- 7) Power up the equipment.
- 8) Touch red probe against second point of test
- 9) Take the reading on the display.



Measurement of Current using Multimeter

- 1) Turn off the power.
- 2) Connect red prob to +ve hole and black to -ve hole.
- 3) The mA socket is often marked with the maximum current, must use 10A socket
- 4) A multimeter must be ~~insert~~ inserted in series in circuit in order to measure current.
- 5) Turn the dial to meter to highest range
- 6) Turn on the power
- 7) If range is too high you can switch to lower range
- 8) Remember to return the +ve probe to the V socket when finished measuring current



Measurement of Resistance Using Multimeter

- 1) If the component is on a circuit board, turn off the power.
- 2) Disconnect one end of the component. This may involve pulling or desoldering. The resistance should be in parallel with the component being measured.
- 3) Connect the probe to +ve ~~to~~ red and -ve to black.
- 4) Turn the dial to lowest Ω range.
- 5) Place a probe tip at each end of the component being measured.
- 6) If the display indicates 1, this means that resistance is greater than can be displayed on the range setting. So must turn dial to the next highest range until a value displayed on L.C.D.

Specification of Multimeter

Specification of Analog Multimeter

- 1) Sensitivity on DC - 25 K ohms/volt
- 2) Voltage Ranges DC - 0 to 0.25, 5, 50, 500V, 0 to 2.5
0 to 125 mV, 2.5 V, 25 V, 250 V and 1.2 K
- 3) DC Current Ranges - 0 to 40 μ A, 2.5 mA
- 4) Sensitivity on AC - 2500 ohms/volt
- 5) AC voltage Ranges - 0-5V, 0-50V
- 6) AC current Ranges - 0-100 mA, 0-500 mA
- 7) Resistance Ranges - Rx1, Rx10, Rx100

8) Accuracy

9) Resistance - $R \times 1$ } $2-5^\circ$
 $R \times 10$ } $R \times 100$ } 2°
 $R \times 1K$ }
 $R \times 10K$ }10) Batteries Required - 1-5V-Type 915
22-5 Type 41211) Operating Temperature - $27^\circ C$ for rated accuracy

Specifications of Digital Multimeter

1) Accuracy

This is the largest allowable error that you DMM occurs under specific operating condition.

2) Resolution

This is the smallest increment of change a DMM can detect and display.

3) Range

DMM range and resolution are related. It provides an autorange function.

4) Display Digits

This is used to describe a DMM's resolution

5) Display Counts

It tell you what a DMM will display before it changes to the next range.

6) The multimeter should have diode check feature

Applications of Multimeter

- 1) Testing Voltage
- 2) Testing Current
- 3) Testing Resistance
- 4) Test batteries
- 5) Test a switch.

Limitations with regard to frequency and Input Impedance

The multimeter has to rectify the AC wave and in doing that applies some capacitors to reduce the ripple in the rectified DC voltage but if frequency is greater than the limit the sample taken is wrong because it takes not just the reading of one period of the almost DC rectified signal but actually takes values of the other periods if the frequency is high.

When used for measuring voltage the input impedance of the multimeter must be very high compared to the impedance of the circuit measured.

otherwise circuit operation may get changed and reading will also be inaccurate.

Lower Sensitivity meter movements are acceptable for testing in circuit where source impedance are low compared to meter impedance.